Camlab Limited – Material Safety Data Sheet

1. Identification

CC/2033-DH Product Code

NITRIC ACID 2.0M (2N) A.R. Product Name

7697-37-2 CAS Number

Supplier:



CAMLAB LIMITED

Norman Way Industrial Estate

Over Cambridge England CB4 5WE

01954 233110 Phone Fax 01954 233101

08:00-17:00 01954 233110 Emergency Telephone

> 24hr 112 (Have this document to hand)

2. Composition

Component	CAS No	EEC No	Conc w/w	Classification & Risk Phrases	Exp (See 8.1)
Nitric acid	7697-37-2	231-714-2	12.6%	C : R8,R35	WEL

3. Hazards Identification



Causes burns.

4. First Aid Measures

Irrigate thoroughly with plenty of water for at least 10 minutes, holding the eye open.

OBTAIN MEDICAL ATTENTION URGENTLY.

Skin Wash off skin thoroughly with water. Remove contaminated clothing immediately and wash

before re-use. OBTAIN MEDICAL ATTENTION URGENTLY.

Remove from exposure. Keep warm and at rest. If there is difficulty in breathing give Inhalation

oxygen if available. If breathing stops or shows signs of failing, apply artificial

resuscitation. If conscious place in a sitting position. OBTAIN MEDICAL ATTENTION URGENTLY.

Ingestion If conscious give plenty of water to drink. Do not induce vomiting. If unconscious place in

the recovery position. OBTAIN MEDICAL ATTENTION URGENTLY.

5. Fire Fighting Measures

Hazards Evacuate area immediately. Keep up wind. Avoid exposure to toxic vapours and fumes. Fire-

fighters should wear protective clothing and breathing apparatus. May evolve toxic fumes if

involved in a fire.

Extinguishing Media

Consider what other flammable materials are present and act accordingly.

Unsuitable

Nothing specified.

6. Accidental Release Measures

Use approved personal protective equipment. Evacuate area immediately. Do not allow general

use of area until it is safe to do so. Protection

6. Accidental Release Measures (continued)

Enviromental Keep non-neutralised material out of sewers, storm drains, surface waters and soil. Notify

the Environmental Agency and local Environmental Health Officer if major spillage occurs.

Major Spillage Contain and absorb on inert material. Transfer absorbent to salvage container for removal.

Wash area down with copious amounts of water.

Minor Spillage Neutralise spill with soda ash, lime, calcium carbonate or sodium bicarbonate. Wash area

down with copious amounts of water.

7. Storage & Handling

Handling Precautions Avoid contact with skin and eyes. Do not breath vapours. Do not allow to contaminate

clothing.

Ensure Local Exhaust Ventilation maintains vapour concentrations below the recommended

limits

Storage Conditions Well ventilated, cool, dry storage .

8.1 Workplace Exposure Limits

Component	CAS No	Workplace Exposure Limits		Maximum Exposure Limits	
		Long Term	Short Term	Long Term	Short Term
		ppm mg m–3	ppm mg m-3	ppm mg m-3	ppm mg m-3
Nitric acid	7697-37-2	2.000 5.200	4.000 10.00		= =

8.2 Personal Protection

Respiratory Use L.E.V. or natural ventilation to maintain vapour concentrations below exposure limits.

If not, use a well maintained chemical cartridge respirator, or use self contained

breathing apparatus.

Hands Use PVC gauntlets.

Eyes Use chemical splash proof glasses or goggles.

Skin If skin contact or contamination of clothing is likely, protective clothing must be worn.

9. Physical & Chemical Properties

Appearance Clear colourless liquid.

Odour Odourless. pH 1 @ 20 °C

Boiling point Aqueous solution
Melting point Aqueous solution
Flash point Not available
Upper Flammable Limit Not available
Lower Flammable Limit Not available
Auto Ignition Not available

Explosive properties No. Oxidising Properties No.

Vapour Presure Not available Relative Density 1.0650 °C

Water Solubility Completely soluble in water.

10. Stability & Reactivity

Chemical Stability Stable under normal conditions

Conditions to Avoid No specific conditions.

Materials to Avoid Reducing agents. Alkalis.

Hazardous May produce hazardous fumes if involved in a fire.

Decomposition Products

11. Toxicological Information

Eyes The liquid is be extremely irritating to eyes and can cause chemical eye burns. Damage can

range from severe irritation and corneal scarring to permanent blindness.

Skin The liquid will cause burns. Dilute solutions will be irritating to the skin.

LD50 Skin Not available

oesophagus. Symptoms may include salivation, thirst, difficulty in swallowing, pain, shock

and vomiting.

LD50 Ingest Not available

Inhalation Presents no significant health hazard by inhalation.

Carcinogenicity Not considered to be a carcinogen.

Mutagenicity No information is available.

Reproductive Effects None identified.

12. Ecological

Acidic, nutrient for undesirable algae.

13. Disposal Considerations

Disposal Methods Dilute in a large excess of water and carefully neutralise with soda ash, then wash to

drain with copious amounts of water.

Contaminated Packaging Very carefully wash out containers with water. Use a licensed waste disposer.

14. Transport Information

Proper Shipping Name Nitric Acid UN Number 2031

UN Classification 8 Corrosive

Subsidiary Risk None

Flash Point Not available

Packing Group II
Transport Category 2
Marine pollutant No
ADR Hazard ID 80



15. Regulatory Information

Labelling Corrosive.

Classification

Label Symbols



Risk & safety Phrases Causes burns. Keep locked up and out of reach of children. Do not breath vapour. In case of

contact with eyes, rinse immediately with plenty of water and seek medical advice. Wear suitable protective clothing. In case of accident or if you feel unwell, seek medical

advice immediately (show the label).

EEC Number 231-714-2

16. Other Information

Document Information

This document has been prepared in accordance with directive 88/379/EEC.

The information contained in this document only covers the hazards presented by this material, it DOES NOT constitute a workplace risk assessment.

Revision Date: 6/11/09.

Data reviewed and PDF file generated: 17/03/10.

Copyright 2010 Camlab Limited.